

FORMERLY UTILIZED SITES REMEDIAL ACTION PROGRAM

POST-REMEDIAL ACTION REPORT FOR BUILDING 14 LINDE SITE

TONAWANDA, NEW YORK

June 1999

VOLUME 1

Prepared by

BECHTEL NATIONAL, INC.

for

U.S. Army Corps of Engineers
Buffalo District
1776 Niagara Street
Buffalo, NY 14207

Contract No. DACW45-98-D-0028

TABLE OF CONTENTS

EXECUTIVE SUMMARY.....	ES-1
TABLES.....	viii
FIGURES.....	ix
ACRONYMS/ABBREVIATIONS	xi

1		
INTRODUCTION.....	1-1	
1.1	PURPOSE.....	1-1
1.2	BACKGROUND.....	1-2
1.2.1	Regulatory Authority Under FUSRAP	1-2
1.2.2	Site History	1-2
1.2.3	Process Description	1-3
1.2.4	Previous Investigations and Remedial Actions.....	1-4
1.2.5	Designation of the Property	1-5
1.3	REMEDIAL ACTION GUIDELINES.....	1-5
1.3.1	Primary Contaminants	1-6
1.3.2	Generic Guidelines and Site-Specific Criteria.....	1-6
1.3.3	Supplemental Limits Approach	1-7
1.3.4	Implementation of ALARA Process.....	1-8
1.4	DOSE ASSESSMENT CALCULATIONS IN SUPPORT OF SUPPLEMENTAL LIMITS.	1-9
1.4.1	Development of Calculation 129-CV-023	1-10
1.4.2	Development of Calculation 129-CV-029	1-11
2		
GENERAL METHODOLOGY.....	2-1	
2.1	DELINEATION APPROACH	2-1
2.1.1	Delineation Surveys	2-1
2.1.2	Remediation Control Surveys	2-2
2.2	REMEDIATION TECHNIQUES	2-2
2.2.1	Sponge Blast	2-2
2.2.2	Shot Blast	2-3
2.2.3	Peel-Away.....	2-3
2.2.4	Mechanical Tools.....	2-3
2.3	POST-REMEDIATION SURVEYS	2-3
2.3.1	Verification Surveys.....	2-3
2.3.2	Final Survey Report	2-4
2.4	IVC SURVEYS AND RELEASE.....	2-4
2.5	SURVEY INSTRUMENTS AND TECHNIQUES.....	2-4
2.5.1	Instrumentation.....	2-4
2.5.2	Survey Techniques	2-6

TABLE OF CONTENTS (continued)

3	
BUILDING EXTERIOR.....	3-1
4	
BUILDING INTERIOR	
4.1	OVERVIEW OF BUILDING 14 REMEDIAL ACTION 4-1
4.1.1	Data Sources 4-1
4.1.2	Structure of Section 4 4-1
4.1.3	Presentation of Results 4-4
4.2	AREAS 2 AND 3 4-5
4.2.1	Area Description and Usage 4-5
4.2.2	Floors 4-5
4.2.3	Subsurface Soil and Other Features 4-6
4.2.4	Overheads/Ceilings 4-7
4.2.5	Walls 4-7
4.2.6	IVC Inspections and Post-Remedial Action Status 4-7
4.2.7	Locations Exceeding Remedial Action Criteria 4-8
4.3	AREA 4 4-8
4.3.1	Area Description and Usage 4-8
4.3.2	Floors 4-9
4.3.3	Subsurface Soil and Other Features 4-9
4.3.4	Overheads and Ceilings 4-9
4.3.5	Walls 4-10
4.3.6	IVC Inspections and Post-Remedial Action Status 4-10
4.3.7	Locations Exceeding Remedial Action Criteria 4-10
4.4	LARGE HALLWAY 4-11
4.4.1	Area Description and Usage 4-11
4.4.2	Floors 4-11
4.4.3	Subsurface Soil and Other Features 4-12
4.4.4	Ceiling 4-12
4.4.5	Walls 4-13
4.4.6	IVC Inspections 4-13
4.4.7	Locations Exceeding Remedial Action Criteria 4-13
4.5	FIRST FLOOR OFFICES AND SMALL HALLWAY 4-14
4.5.1	Area Description and Usage 4-14
4.5.2	Floors 4-14
4.5.3	Soil 4-14
4.5.4	Ceilings and Overheads 4-15
4.5.5	Walls 4-15
4.5.6	IVC Inspections 4-16
4.5.7	Locations Exceeding Remedial Action Criteria 4-16
4.6	SECOND FLOOR 4-16
4.6.1	Area Description and Usage 4-16
4.6.2	Floors 4-16
4.6.3	Ceilings and Overheads 4-17

TABLE OF CONTENTS (continued)

4.6.4	Walls	4-17
4.6.5	IVC Inspections	4-17
4.6.6	Locations Exceeding Remedial Action Criteria.....	4-17
4.7	AREAS 8, 10, AND 11	4-18
4.7.1	Area Description and Usage	4-18
4.7.2	Floors.....	4-18
4.7.3	Subsurface Soil and Trenches.....	4-19
4.7.4	Ceilings and Overheads.....	4-20
4.7.5	Walls	4-20
4.7.6	IVC Inspections	4-20
4.7.7	Locations Exceeding Remedial Action Criteria.....	4-20
4.8	CORRIDOR.....	4-21
4.8.1	Area Description and Usage	4-21
4.8.2	Floors.....	4-21
4.8.3	Subsurface Soil and Other Features	4-22
4.8.4	Ceiling	4-23
4.8.5	Walls	4-23
4.8.6	IVC Inspections	4-24
4.8.7	Locations Exceeding Remedial Action Criteria.....	4-24
4.9	AREA 9.....	4-24
4.9.1	Area Description and Usage	4-24
4.9.2	Floors.....	4-25
4.9.3	Soil	4-25
4.9.4	Trenches and Drainpipes.....	4-26
4.9.5	Ceilings and Overheads.....	4-27
4.9.6	Walls	4-28
4.9.7	IVC Inspections	4-29
4.9.8	Locations Exceeding Remedial Action Criteria	4-30
4.10	AREAS 12 AND 13.....	4-30
4.10.1	Area Description and Usage	4-30
4.10.2	Floors.....	4-31
4.10.3	Subsurface Soil	4-31
4.10.4	Trenches and Pedestal.....	4-34
4.10.5	Ceiling	4-34
4.10.6	Walls	4-35
4.10.7	Crane and Crane Rails	4-35
4.10.8	Stairwell, Sump, and Sump Drainlines.....	4-36
4.10.9	IVC Inspections	4-37
4.10.10	Locations Exceeding Remedial Action Criteria	4-38
4.11	AREA 14 NORTH	4-38
4.11.1	Area Description and Usage	4-39
4.11.2	Floors.....	4-39
4.11.3	Soil and Other Subsurface Features	4-39
4.11.4	Ceiling	4-41
4.11.5	Crane Rails	4-41
4.11.6	Walls	4-42
4.11.7	IVC Inspections	4-42
4.11.8	Locations Exceeding Remedial Action Criteria	4-43
4.12	AREA 14 SOUTH	4-43
4.12.1	Area Description and Usage	4-43

TABLE OF CONTENTS (continued)

4.12.2	Floors.....	4-44
4.12.3	Subsurface Soil and Other Features	4-44
4.12.4	Walls	4-45
4.12.5	Ceiling	4-49
4.12.6	Crane and Crane Rails	4-50
4.12.7	IVC Inspections	4-50
4.12.8	Locations Exceeding Remedial Action Criteria	4-52
4.13	AREA 15.....	4-53
4.13.1	Area Description and Usage	4-53
4.13.2	Floors.....	4-53
4.13.3	Subsurface Soil and Trenches.....	4-54
4.13.4	Ceiling and Overheads.....	4-55
4.13.5	Walls	4-56
4.13.6	Crane and Crane Rails	4-56
4.13.7	IVC Inspections	4-56
4.13.8	Locations Exceeding Remedial Action Criteria	4-57
4.14	AREA 20A WEST.....	4-57
4.14.1	Area Description and Usage	4-57
4.14.2	Floors.....	4-58
4.14.3	Subsurface Soil and Other Features	4-58
4.14.4	Ceilings and Overheads.....	4-59
4.14.5	Walls	4-59
4.14.6	IVC Inspections and Post-Remedial Action Status.....	4-59
4.14.7	Locations Exceeding Remedial Action Criteria.....	4-59
4.15	AREAS 20A-EAST, 20B, 20B-1, AND 20C.....	4-60
4.15.1	Area Description and Usage	4-60
4.15.2	Floors.....	4-60
4.15.3	Subsurface Soil and Other Features	4-61
4.15.4	Walls	4-62
4.15.5	Overheads	4-62
4.15.6	IVC Inspections	4-62
4.15.7	Locations Exceeding Remedial Action Criteria.....	4-63
4.16	AREA 21.....	4-64
4.16.1	Area Description and Usage	4-64
4.16.2	Floors.....	4-65
4.16.3	Subsurface Soil and Other Features	4-65
4.16.4	Walls	4-66
4.16.5	Ceilings and Overheads.....	4-66
4.16.6	IVC Inspections and Post-Remedial Action Status.....	4-67
4.16.7	Locations Exceeding Remedial Action Criteria.....	4-67
4.17	PROCESS PIPING	4-68
4.17.1	Background and Overview	4-68
4.17.2	Scope of Investigation	4-68
4.17.3	Survey Methodology.....	4-69
4.17.4	Summary of Survey Results.....	4-69
4.17.5	IVC Inspections	4-69
4.17.6	Locations Exceeding Remedial Action Criteria.....	4-70
4.18	RADON SURVEY.....	4-70
4.18.1	Methodology	4-70

TABLE OF CONTENTS (continued)

4.18.2	Sample Locations	4-70
4.18.3	Results	4-71
4.19	IN-BED DRAINLINES.....	4-71
4.19.1	Description	4-71
4.19.2	Investigation Results	4-72
4.19.3	Remedial Activities	4-73
4.19.4	Locations Exceeding Remedial Action Criteria	4-74
5		
SUMMARY AND CONCLUSIONS		5-1
5.1	SUMMARY OF WORK PERFORMED.....	5-1
5.1.1	Scope and Objective	5-1
5.1.2	Methodologies and Work Execution	5-1
5.1.3	Description of Delineation and Remedial Activities.....	5-2
5.2	SUMMARY OF RESULTS.....	5-7
5.2.1	Verification Surveys and Samples	5-7
5.2.2	Locations Exceeding Remedial Action Criteria	5-8
5.3	COST	5-8
5.4	CONCLUSIONS.....	5-8

REFERENCES

APPENDIXES

- A IDM Survey Log**
- B IDM Delineation Surveys**
- C IDM Verification Surveys**
- D IDM Verification Survey Results**
- E IDM Sample Radiological Analytical Results**
- F Process Piping Report**
- G IVC Letters**
- H IVC and SEC Surveys**
- I Photographs**
- J Resolution of Comments on the Draft PRAR**

TABLE OF CONTENTS (continued)

TABLES

- 1-1 Summary of Remedial Criteria and Guidelines
- 1-2 Background Concentrations of Radionuclides in Soil
- 1-3 Summary of Exposure Parameters for Calculation 129-CV-023
- 1-4 Assumed Levels of Average Residual Radioactive Contamination for Calculation 129-CV-023 and 129-CV-029
- 1-5 Results of Dose Assessment Calculation for Floors, Walls, and Overheads
- 1-6 Summary of Exposure Parameters for Calculation 129-CV-029
- 1-7 Results of Dose Assessment Calculation for In-Bed Drainlines—Scenario #1
- 1-8 Results of Dose Assessment Calculation for In-Bed Drainlines—Scenario #2
- 4.2-1 Summary of Soil and Miscellaneous Sample Results for Areas 2 and 3
- 4.3-1 Summary of Soil Sample Results for Area 4
- 4.4-1 Summary of Soil Sample Results for the Large Hallway
- 4.5-1 Summary of Soil Samples from the First Floor Offices and Small Hallway
- 4.7-1 Summary of Soil and Miscellaneous Sample Results for Areas 8, 10, and 11
- 4.8-1 Summary of Soil and Miscellaneous Sample Results for the Corridor
- 4.9-1 Summary of Soil and Miscellaneous Sample Results for Area 9
- 4.9-1 Summary of Soil and Miscellaneous Sample Results from Areas 12 and 13
- 4.11-1 Summary of Soil and Miscellaneous Sample Results from Area 14 North
- 4.12-1 Summary of Soil and Miscellaneous Sample Results from Area 14 South
- 4.13-1 Summary of Soil and Miscellaneous Sample Results for Area 15
- 4.14-1 Summary of Soil Sample Results for Area 20A-West
- 4.15-1 Summary of Soil Samples from Areas 20A-East, 20B, 20B-1, and 20C
- 4.16-1 Summary of Soil Sample Results for Area 21
- 4.17-1 Summary of Process Piping Breaches
- 4.18-1 Summary of Radon Monitoring Locations and Results, Linde Site Building 14
- 4.19-1 Summary of In-Bed Drainline Delineation Data
- 5-1 Summary of Locations Exceeding Remedial Action Criteria

TABLE OF CONTENTS (continued)

FIGURES

- 1-1 Location of the Linde Site, Tonawanda, New York
- 1-2 Plan View of the Linde Site
- 1-3 Uranium Ore Processing at the Linde Site

- 4.2-1 Areas 2 and 3, Summary of Contamination and Remedial Results
- 4.2-2 Areas 2 and 3, Post-Remedial Verification Survey Results: Floor
- 4.2-3 Areas 2 and 3, Post-Remedial Verification Survey Results: Ceiling
- 4.2-4 Areas 2 and 3, Post-Remedial Verification Survey Results: Walls

- 4.3-1 Area 4, 4A, and 4B, Summary of Contamination and Remedial Results
- 4.3-2 Area 4, Post-Remedial Verification Survey Results: Floor
- 4.3-3 Area 4, Post-Remedial Verification Survey Results: Ceiling
- 4.3-4 Areas 4 (Main), 4A and 4B, Post-Remedial Verification Direct Survey Results: Walls
- 4.3-5 Areas 4 (Main), 4A and 4B, Post-Remedial Verification Removable Survey Results: Walls

- 4.4-1 Large Hallway, Summary of Remedial Activities
- 4.4-2 Large Hallway, Post-Remedial Verification Survey Results: Floor
- 4.4-3 Large Hallway, Post-Remedial Verification Survey Results: Ceiling
- 4.4-4 Large Hallway, Post-Remedial Verification Survey Results: Walls

- 4.5-1 First Floor Offices and Small Hallway, Summary of Contamination and Remedial Actions
- 4.5-2 First Floor Offices, Post-Remedial Verification Survey Results: Floor
- 4.5-3 First Floor Offices, Post-Remedial Verification Survey Results: Ceiling
- 4.5-4 First Floor Offices, Post-Remedial Verification Survey Results: West Walls
- 4.5-5 First Floor Offices, Post-Remedial Verification Survey Results: East Walls
- 4.5-6 First Floor Offices, Post-Remedial Verification Survey Results: Small Hallway
- 4.5-7 First Floor Offices, Post-Remedial Verification Survey Results: North Walls
- 4.5-8 First Floor Offices, Post-Remedial Verification Survey Results: South Walls
- 4.5-9 First Floor Offices, Post-Remedial Verification Survey Results: Women's Room Walls

- 4.6-1 Second Floor Offices, Post-Remedial Verification Survey Results: Floor
- 4.6-2 Second Floor Offices, Post-Remedial Verification Survey Results: Ceiling
- 4.6-3 Second Floor Offices, Post-Remedial Verification Survey Results: Small Office Walls
- 4.6-4 Second Floor Offices, Post-Remedial Verification Survey Results: HVAC Room, Stairwells, and Room 211 Walls

- 4.7-1 Areas 8, 10, 11, and Corridor, Summary of Delineation Data and Remedial Activities
- 4.7-2 Areas 8, 10, and 11, Post-Remedial Verification Survey Results: Floor
- 4.7-3 Areas 8, 10, and 11, Post-Remedial Verification Survey Results: Ceiling
- 4.7-4 Areas 8, 8B, and Area 10, Post-Remedial Verification Survey Results: South and East Walls
- 4.7-5 Areas 8, 8B, and Area 10, Post-Remedial Verification Survey Results: North and West Walls
- 4.8-1 Corridor, Post-Remedial Verification Survey Results: Ceiling and Floors
- 4.8-2 Corridor Area, Post-Remedial Verification Survey Results: West and North Walls
- 4.8-3 Corridor Area, Post-Remedial Verification Survey Results: East and South Walls

- 4.9-1 Area 9, Summary of Remedial Activities
- 4.9-2 Area 9, Post-Remedial Verification Survey Results: Floor

TABLE OF CONTENTS (continued)

- 4.9-3 Area 9, Post-Remedial Verification Survey Results: Ceiling
 - 4.9-4 Area 9, Post-Remedial Verification Survey Results: East and South Walls
 - 4.9-5 Area 9, Post-Remedial Verification Survey Results: West and North Walls
 - 4.9-6 Areas 8a and Areas 9A-9D, Post-Remedial Verification Direct Survey Results: Walls
 - 4.9-7 Areas 8a and Areas 9A-9D, Post-Remedial Verification Removable Survey Results: Walls

 - 4.10-1 Area 12 and 13, Summary of Remedial Activities (Floors)
 - 4.10-2 Area 12 and 13, Post Remedial Verification Survey Results: Floor
 - 4.10-3 Area 12 and 13, Summary of Remedial Activities (Locations Exceeding Remedial Action Criteria)
 - 4.10-4 Area 12 and 13, Post Remedial Verification Survey Results: Ceiling
 - 4.10-5 Area 12 and 13, Post Remedial Verification Survey Results: West Walls
 - 4.10-6 Area 12 and 13, Post Remedial Verification Survey Results: East Walls
 - 4.10-7 Area 12 and 13, Post Remedial Verification Survey Results: North and South Walls

 - 4.11-1 Area 14 North, Summary of Remedial Activities
 - 4.11-2 Area 14 North, Post-Remedial Verification Survey Results: Floor
 - 4.11-3 Area 14 North, Post-Remedial Verification Survey Results: Ceiling
 - 4.11-4 Area 14 North, Post-Remedial Verification Survey Results: Walls

 - 4.12-1 Area 14 South, Summary of Remedial Activities (Floors)
 - 4.12-2 Area 14 South, Post-Remedial Verification Survey Results: Floor
 - 4.12-3 Area 14 South, Summary of Remedial Activities (Walls)
 - 4.12-4 Area 14 South, Post-Remedial Verification Survey Results: North Wall
 - 4.12-5 Area 14 South, Post-Remedial Verification Survey Results: South Wall
 - 4.12-6 Area 14 South, Post-Remedial Verification Survey Results: East and West Walls
 - 4.12-7 Area 14 South, Post-Remedial Verification Survey Results: Ceiling

 - 4.13-1 Area 15, Summary of Remedial Activities
 - 4.13-2 Area 15, Post-Remedial Verification Survey Results: Floor
 - 4.13-3 Area 15, Post-Remedial Verification Survey Results: Ceiling
 - 4.13-4 Area 15, Post-Remedial Verification Survey Results: South and East Walls
 - 4.13-5 Area 15, Post-Remedial Verification Survey Results: North and West Walls
 - 4.13-6 Areas 15A, 15B and 15B-1, Post-Remedial Verification Removable Survey Results: Walls
 - 4.13-7 Areas 15A, 15B and 15B-1, Post-Remedial Verification Direct Survey Results: Walls

 - 4.14-1 Area 20A-West, Soil Boring Locations and Conceptual Illustration of Contamination
 - 4.14-2 Area 20A-West, Post-Remedial Verification Survey Results: Floor
 - 4.14-3 Area 20A-West, Post-Remedial Verification Survey Results: Ceiling
 - 4.14-4 Area 20A-West, Post-Remedial Verification Survey Results: Walls

 - 4.15-1 Area 20A-East, 20B, 20B-1, and 20C, Conceptual Illustration of Contamination

 - 4.16-1 Area 21, Summary of Features, Contamination, and Post-Remedial Conditions

 - 4.18-1 Radon Sample Location Map

 - 4.19-1 Location of In-Bed Drainlines

 - 5-1 Locations Exceeding Remedial Action Criteria
-

ACRONYMS/ABBREVIATIONS

AEC	Atomic Energy Commission
ALARA	as low as reasonably achievable
ANL	Argonne National Laboratory
BNI	Bechtel National, Inc.
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act
DOE	U.S. Department of Energy
EPA	U.S. Environmental Protection Agency
FBDU	Ford, Bacon, and Davis Utah, Inc.
FUSRAP	Formerly Utilized Sites Remedial Action Program
G-M	Geiger-Mueller
HVAC	heating, ventilation, and air conditioning
IVC	independent verification contractor
LEC	location exceeding criteria
MDA	minimum detectable activity
MED	Manhattan Engineer District
NEPA	National Environmental Policy Act
NRC	U.S. Nuclear Regulatory Commission
NYSDEC	New York State Department of Environmental Conservation
ORNL	Oak Ridge National Laboratory
PRAR	post-remedial action report
RI	remedial investigation
RI/FS-EIS	remedial investigation/feasibility study-environmental impact statement
TNU	Thermo Nutech, Inc.
USACE	U.S. Army Corps of Engineers
WL	working level